**Surface Temperature Probes** The following probes are suitable for measuring temperatures on a variety of surfaces. Griddles or grills may be checked to ensure proper cooking temperatures. Various types of equipment including motors, compressors, or plastic molds may be monitored for proper operation.

